

Index

A

Alloy steels. *See* Carbon and alloy steels

Alloying

aluminum and aluminum alloys . . . 351–416
austenitic manganese steels 242–253
carbon and alloy steels 123–253
cast irons 21–119
cemented carbides and cermets 573–586
cobalt and cobalt alloys 540–549
compact graphite irons 91–99
copper and copper alloys 457–494
ductile irons 62–90
electrical contact alloys 596–613
gray irons 21–61
high-alloy white irons 107–119
high-strength low-alloy steels 193–209
lead, tin, and their alloys 528–539
low-expansion alloys 587–595
magnesium and magnesium alloys 432–453
magnetic alloys 614–632
malleable irons 100–106
maraging steels 234–241
for mechanical properties 3–8
nickel and nickel alloys 495–519
noble metal alloys 550–569
ordered intermetallics 337–348
for physical properties 12–14
principles 3–17
for processing properties 10–12
properties, effect of 14–15
refractory metal alloys 308–336
for service properties 8–10
stainless steels 257–289
superalloys 290–307
surface 16–17
techniques 15–16
titanium and titanium alloys 417–431
tool steels 210–233
zinc and zinc alloys 520–527

Aluminum

in austenitic manganese steels 253
in carbon and alloy steels 140, 154,
154(F), 159, 176, 180

in cobalt alloys 547(T), 548(T)
in compacted graphite irons 94, 98, 99(F)
in copper alloys 458(T), 459(T), 460(T),
461(T), 462, 466–467, 469(T), 472–473,
475–476, 477, 478(F,T), 481, 482–483,
484(T), 485(F), 486, 488, 488(T)
in ductile irons 69(T), 72
in gray irons 28(T)
in high-strength low-alloy steels 209
in magnesium alloys 434(T),
435, 436(T), 437, 438, 440–441, 442(F),
446–448, 446(F), 447(F), 448(F), 449(F),
450(F), 451
in magnetic alloys 617(F), 618(F), 620,
629(T), 630, 630(T)
in malleable irons 103(T), 104
in maraging steels 236(T)
in molybdenum alloys 310(T), 311(T)
in nickel alloys 498–500(T), 502(T), 503,
510, 513, 517
in ordered intermetallics 339(T), 343(T)
in solder alloys 535(T), 536
in stainless steels 257, 258(F), 262(F),
269(T), 282(T)
in superalloys 292(F), 293(F), 294(T),
295–296(T), 297(T), 301, 305(T), 306(F)
in tin-base bearing alloys 539
in titanium alloys 419, 419(T), 420,
422(T), 428–429, 430, 430(F), 431
in tungsten alloys 315
in zinc alloys 521(T), 522(T), 523,
524(F), 525(T), 526

Aluminum and aluminum alloys

alloying elements 366–416, 367(F),
368(F,T)
applications 355, 358(T), 359(T)
brazeability 413–414, 414(T), 415(T)
cast alloys 352–354, 355(T), 357(T),
359(T), 364–366, 364(F), 400–401,
402–404, 416
characteristics 351–352
classification 352–366, 354(T)
compositions 356(T), 357(T)
corrosion behavior 398–404, 400(F)
forgeability 410, 411(F)

Aluminum and aluminum alloys (continued)

- formability 407–409, 409(F), 410(F)
- grain refiners 390–392, 391(F), 392(F)
- hypereutectic Al-Si alloys, phosphorus refinement 397, 398(F)
- hypoeutectic Al-Si alloys, modification and refinement. 392–397, 393(F), 394(F), 395(F), 396(F)
- machineability 411–412
- phase formation 387–390
- processing 407–416
- product forms 356(T)
- properties 355(T), 369(F), 370(F), 374(F), 375(F), 376(F), 377(F), 378(F), 379(F), 381(F), 382(F), 386(F), 387(F), 396(F)
- second-phase constituents 368–370
- solderability 414–416
- wear behavior 404–407, 405(T)
- weldability 412–413
- wrought alloys 352–353, 354(T), 355(T), 356(T), 357, 358(T), 359–363, 360(F), 361(F), 362(F), 363(F), 399–404, 412–416

Antimony

- in aluminum alloys 371, 392–395, 412
- in carbon and alloy steels 142, 157, 164–169, 165(F), 166(F), 167(F)
- in copper alloys 478(T), 481
- in ductile irons 69(T), 72
- in gray irons 28(T)
- in lead alloys 529–530(T), 531(T), 532(T), 533(T)
- in malleable irons 103(T)
- in solder alloys 535(T), 536–537, 538
- in superalloys 302(T)
- in tin-base bearing alloys 539(T)

Argon, in superalloys 302(T)

Arsenic

- in aluminum alloys 371
- in carbon and alloy steels 142, 157, 164–169, 165(F), 166(F), 168(F)
- in compacted graphite irons 98
- in copper alloys 462, 478(T), 481, 486
- in ductile irons 69(T), 72
- in gray irons 28(T)
- in lead alloys 529–530(T), 533(T)
- in malleable irons 103(T)
- in solder alloys 535(T), 537
- in superalloys 302(T)
- in tin-base bearing alloys 539

Austenitic manganese steels

- alloying elements 248–252
- applications 242
- composition requirements and control 243–248, 243(T)
- special grades 252–253

B**Barium**

- in ductile irons 69(T)
- in lead alloys 529–530(T)

Beryllium

- in aluminum alloys 371
- in copper alloys 463–464, 471, 478(F,T), 484(T), 486, 488(T), 601(T)
- in magnesium alloys 438, 442
- in nickel alloys 503

Bismuth

- in aluminum alloys 371, 404, 411
- in austenitic manganese steels 251, 252
- in carbon and alloy steels 141, 189
- in copper alloys 458(T), 473, 487, 490, 492
- in ductile irons 69(T), 72
- in gray irons 28(T)
- in high-alloy white irons 119
- in malleable irons 103(T), 104
- in solder alloys 535(T), 537
- in superalloys 302(T)
- in tin-base bearing alloys 539

Boron

- in aluminum alloys 372, 390–392, 391(F)
- in carbon and alloy steels 124(T), 140, 149, 150(F), 155, 156(F), 175(T)
- in cobalt alloys 547(T), 548(T)
- in copper alloys 478(T)
- in ductile irons 69(T), 72
- in gray irons 28(T)
- in high-alloy white irons 112(F)
- in magnetic alloys 629(T), 630(T), 632
- in malleable irons 103(T), 104
- in nickel alloys 498–500(T), 514, 517
- in ordered intermetallics 339(T), 343(T), 344(T)
- in stainless steels 282(T)
- in superalloys 293(F), 294(T), 297(T), 301, 302(T)

C**Cadmium**

- in aluminum alloys 372
- in copper alloys 462, 463, 478(F,T), 487, 488(T), 601(T)
- in lead alloys 529–530(T)
- in magnesium alloys 442(F), 450(F)
- in silver alloys 551, 552–553, 552(T), 598(F), 599–600, 599(T)
- in solder alloys 535(T), 537
- in zinc alloys 521(T), 522(T), 525, 525(T), 526

- Cadmium oxide**, in silver-base composites 609(T), 611, 612, 612(F)
- Calcium**
 in aluminum alloys 372, 392–395
 in austenitic manganese steels 252
 in carbon and alloy steels 141, 156, 158(F), 161(F), 188
 in compacted graphite irons 94
 in copper alloys 478(T)
 in ductile irons 69(T)
 in high-strength low-alloy steels 194
 in lead alloys 529–530(T), 531(T)
 in magnesium alloys 438, 442(F)
 in malleable irons 103(T)
 in superalloys 302(T)
- Carbides, cemented.** *See* Cemented carbides
- Carbon**
 in aluminum alloys 372
 in austenitic manganese steels 242, 243–248, 243(T), 244(F), 245(F), 252
 in carbon and alloy steels 123–137, 125(T), 126(T), 131(T), 134(T), 135–136(T), 138(F), 143–144, 143(F), 145–148, 147(F), 148(F), 150, 151(F), 159, 160(F), 175, 175(T), 177–178, 177(F), 181(T), 182–184, 182(F), 185–187, 186(F), 190
 in cobalt alloys 542, 542(T), 543–547, 547(T), 548, 548(T)
 in compacted graphite irons 93, 93(F), 97(F)
 in ductile irons 65–66(T), 68–70, 69(T), 79(T), 80(T)
 in gray irons 24–26, 26(F), 32, 52(T), 59(T)
 in high-alloy white irons 108, 108(T), 109, 110, 111, 113(F)
 in high-strength low-alloy steels 193, 194, 197, 208
 in low-expansion alloys 588, 590(F), 592(T)
 in magnetic alloys 615–616, 616(F), 618–619
 in malleable irons 102, 102(T), 103(T), 104
 in maraging steels 234, 240
 in molybdenum alloys 310(T), 311(T)
 in nickel alloys 498–500(T), 502(T), 510, 514, 516–517
 in ordered intermetallics 343(T), 344(T)
 in silver-base composites 609–610(T), 610–612
 in stainless steels 257, 258(F), 260(T), 261(T), 262(F), 263(T), 264(F), 265(T), 266(T), 267(F), 268(T), 269(T), 270, 274(F), 278(F), 282(T)
 in superalloys 293(F), 294(T), 295–296(T), 297(T), 302(T)
 in tantalum alloys 325(T)
 in titanium alloys 419, 422(T), 428
 in tool steels 211–212(T), 214, 218, 219, 220, 221, 222, 223, 224, 230, 233
- Carbon and alloy steels.** *See also* Austenitic manganese steels; High-strength low-alloy steels; Maraging steels; Tool steels
 alloy steel classifications 130–133
 alloying elements 134–141, 135–136(T), 138(F)
 applications 123, 127–130, 132–133
 carbon steel classifications 123–130
 compositions 125(T), 126(T), 131(T), 132(T), 133(T), 134(T), 170(T)
 corrosion resistance 135–136(T), 169–176, 171(F), 172(T), 173(F), 174(F), 175(T)
 designations 124(T)
 fatigue resistance 135–136(T), 159–161, 160(F), 161(F)
 forgeability 180, 181(F,T)
 formability 178–180
 hardenability 135–136(T), 143–149, 143(F), 145(F), 147(F), 148(F), 150(F)
 high-temperature service 135–136(T), 162–163, 163(F)
 low-temperature service 135–136(T), 162, 162(F)
 machinability 185–191, 186(F,T), 187(T), 188(F), 190(T)
 mechanical properties 126(T), 131(T), 132(T), 133(T), 135–136(T), 138(F)
 notch toughness 135–136(T), 150–159, 151(F), 152(F), 153(F), 154(F), 156(F), 157(F), 158(F), 159(F), 160(F)
 for pressure vessels and piping 132–133, 132(T), 133(T)
 residual elements 141–142
 temper embrittlement 164–169, 165(F), 166(F), 167(F), 168(F)
 wear resistance 176–178, 177(F)
 weldability 181–185, 182(F)
- Cast irons.** *See* Compacted graphite irons; Ductile irons; Gray irons; High-alloy white irons; Malleable irons
- Cemented carbides.** *See also* Cermets
 binder content 577(T), 578–582
 compositions 575(T), 578–582
 corrosion resistance 581–582, 582(F)
 grain size 575(T), 576(F), 577(F,T), 578–582, 579(F), 580(F)
 machining applications 574–576
 microstructures 576(F), 577(F)
 nonmachining applications 577, 577(T)
 overview 573
 processing 574
 properties 575(T), 577(T), 578–582, 579(F), 580(F), 581(F), 582(F)

Cerium

- in aluminum alloys 373
- in carbon and alloy steels 141, 180
- in ductile irons 72
- in magnesium alloys 450(F)
- in malleable irons 103(T)
- in superalloys 293(F), 294(T), 302(T)

Cermets. *See also* Cemented carbides

- machining applications 582–583
- overview 574
- processing 574
- properties 583(F), 584(T)
- steel-bonded carbides in . . . 584–585, 584(T), 585(T)

Chromium

- in aluminum alloys 356(T), 368(F), 373, 389–390, 403, 410, 411
- in austenitic manganese steels 243(T), 248–250, 249(F), 252
- in carbon and alloy steels 124(T), 130, 132, 139, 155, 162, 163, 164–169, 165(F), 166(F), 167(F), 168(F), 172(T), 173–174, 174(F), 175(T), 176, 179, 185, 190
- in cermets 585
- in cobalt alloys 542(T), 544, 547(T), 548, 548(T)
- in copper alloys 463, 464, 471, 478(T), 487, 488, 488(T)
- in ductile irons 69(T), 72, 73
- in gray irons 28(T), 30–31, 31(T), 46(F), 47(F), 49, 51(T), 52(T), 59(T)
- in high-alloy white irons . . . 107, 108, 108(T), 109, 109(F), 114–115, 116(F)
- in high-strength low-alloy steels 193
- in low-expansion alloys 588, 589(F), 590(F), 592–593, 593(T), 594, 595(T)
- in magnetic alloys 617(F), 618, 618(F), 624–625, 626, 626–627(T), 627, 629(T), 630(T)
- in malleable irons 103(T), 104
- in nickel alloys 498–500(T), 502(T), 504–507, 511, 512, 513, 515, 518–519
- in ordered intermetallics 339(T), 343(T), 344(T)
- in stainless steels 257, 258(F), 260(T), 261(T), 262(F), 263(T), 264(F), 265(T), 266(T), 267(F), 268(T), 269–270, 269(T), 273(F), 274(F), 276(T), 277(T), 282(T), 287(F)
- in superalloys 293(F), 294(T), 295–296(T), 297(T), 301, 305(T)
- in titanium alloys 419(T), 420, 427, 430, 431
- in tool steels 210, 211–212(T), 215, 219, 220, 221, 222, 223, 224, 228, 230
- in zinc alloys 524–525

Chromium carbide, in cemented

- carbides and cermets 573, 583

Cobalt

- in aluminum alloys 373
- in cemented carbides 573–582, 575(T), 576(F), 577(F,T), 579(F), 580(F), 581(F), 582(F)
- in copper alloys 463, 478(T), 601(T)
- in low-expansion alloys 588, 589(F), 593–594, 594(T)
- in magnesium alloys 442(F)
- in magnetic alloys 617, 617(F), 618(F), 625–626, 625(F), 626–627(T), 628, 629(T), 630, 630(T), 631
- in maraging steels 234, 236, 236(T), 237–239, 238(T), 239, 239(F), 240(F)
- in nickel alloys 498–500(T), 502(T), 509, 512, 513
- in palladium alloys 568
- in stainless steels 264(F), 282(T)
- in superalloys 292(F), 293(F), 294(T), 295–296(T), 297(T), 298
- in titanium alloys 420
- in tool steels 211–212(T), 214, 216, 217(F), 218(F), 224, 227
- in tungsten alloys 318–319

Cobalt and cobalt alloys

- alloying elements 543–549, 547(T)
- applications 540–543, 541(T)
- carbides 543–547
- compositions 542(T), 548(T)
- corrosion resistance 548–549
- crystal structure 540
- heat resistance 546–547, 547(T), 548(T)
- properties 540
- wear resistance 543–546

Color chart, for gold-silver-copper

- alloys 14(F)

Compacted graphite irons

- alloying elements 94–96, 95(F), 96(F)
- applications 91–93
- composition requirements
 - and control 93–96, 93(F), 94(T)
- graphite morphology 91, 92(F), 94
- melt treatment elements 94, 94(T)
- properties 96–98, 97(F), 98(F,T), 99(F)

Copper

- in aluminum alloys 356(T), 357(T), 359, 365–366, 368(F,T), 373–376, 374(F), 375(F), 377, 377(F), 389, 400–401, 400(F), 403–404, 406, 408–409, 410, 412–413, 415
- in austenitic manganese steels 251, 252
- in carbon and alloy steels 123, 132, 139, 155–156, 169, 170–171, 171(F), 172, 172(T), 175(T), 176, 179
- in compacted graphite irons . . . 94, 95(F), 98, 98(F)
- in ductile irons 69(T), 72, 76(F), 78(F), 80(T)

in gold alloys . . . 555–556, 556(T), 602–603, 602(T)
 in gray irons . . . 27, 28(T), 30, 31, 31(T), 50, 51(T), 52(T), 59(T)
 in high-alloy white irons. . . 107, 108(T), 117
 in high-strength low-alloy steels . . . 193, 194
 in lead alloys 529–530(T)
 in low-expansion alloys 588, 590(F)
 in magnesium alloys. . . 434(T), 436(T), 438, 441, 442(F), 443(F), 444(T), 445(T)
 in magnetic alloys . . . 618, 618(F), 624–625, 628, 629(T), 630, 630(T), 631
 in malleable irons. 103(T), 105
 in nickel alloys . . . 498–500(T), 502(T), 503, 507, 513, 515, 518
 in palladium alloys 566(F), 567–568, 605(T), 606, 608
 in platinum alloys 588(F), 604(F)
 in silver alloys 551–552, 552(T), 553, 554–555, 554(F), 565, 597–599, 598(F), 599(T), 600
 in solder alloys. 535(T), 537, 538
 in stainless steels. 257, 258(F), 264(F), 268(T), 284(F)
 in superalloys 302(T)
 in tin-base bearing alloys. 539(T)
 in titanium alloys 419(T), 420, 430
 in zinc alloys . . . 521(T), 522(T), 524, 525(T), 526

Copper and copper alloys

age-hardening alloys 463–464, 471
 alloying elements 477–494
 applications. 457–458
 brasses 464–466, 471–473, 480–481
 brazability 488, 488(T)
 bronzes 466–467, 473–476, 481–482, 482–483
 cast alloys 458(T), 468–477
 castability 493–494
 characteristics 457–458
 classification 458(T), 459–477
 compositions. 458(T), 460(T), 468–470, 469(T), 601(T)
 copper-nickels 467–468, 476, 482
 coppers 462, 463(F), 470, 479–480
 corrosion resistance. 479–486
 designations 458–459, 458(T)
 electrical conductivity. . . 477–479, 478(F,T), 479(F), 480(F)
 electrical contact alloys . . . 600–601, 601(T), 608, 610–611, 610(T)
 high-copper alloys 463–464, 470–471, 479–480
 leaded coppers . . . 476–477, 489–490, 489(F)
 machinability 489–492, 490(F), 491(F)
 nickel silvers. 468, 476, 482
 properties 460(T), 461(T), 601(T)
 solderability. 488, 488(T)

special alloys 477
 stress-corrosion cracking . . 483–486, 484(T), 485(F)
 weldability 486–488
 workability. 492–493, 493(F)
 wrought alloys . . . 458(T), 459–468, 460(T), 461(T)

D

Ductile irons

alloying elements. 68–73, 69(T), 71(F)
 applications 65–66(T), 67–68
 austempering 80–81, 80(T)
 austenitic nickel-alloyed 81–86, 82(T), 83(F), 84(F,T), 85(F,T), 86(F)
 composition control 68–73
 compositions. 65–66(T), 82(T)
 corrosion resistance . . . 81, 82, 85(T), 86–87
 elevated-temperature properties 81–82, 83(F), 84(F), 87–89, 88(F), 89(F)
 hardenability . . . 72, 74–75, 75(F), 76–77(F), 78(F), 79(F)
 high-silicon 86–89, 87(F), 88(F), 89(F)
 inoculation 73–74
 magnesium treatment 73
 microstructure 62–63, 63(F), 64(F)
 normalizing 75, 79–80, 79(F)
 scaling and growth. 82, 84(T)
 specifications. 63–67, 65–66(T), 67(T)
 spheroidal graphite 63(F), 64(F)
 stress-rupture 85(F)
 thermal expansion 86, 86(F)
 wear resistance 82, 84

E

Electrical contact alloys

composites . . . 608–612, 609–610(T), 612(F)
 compositions 599(T), 601(T), 602(T), 605(T), 609–610(T)
 copper-base 600–601, 601(T), 608, 610–611, 610(T)
 gold-base 601–603, 602(T)
 material requirements 596–597
 palladium-base 603, 605(T), 606–608, 607(F)
 platinum-base 603–605, 604(F), 605(T)
 properties . . . 598(F), 599(T), 601(T), 602(T), 604(F), 605(T), 607(F), 609–610(T), 612(F)
 silver-base. 597–600, 598(F), 599(T), 608–612, 609–610(T), 612(F)

G**Gallium**

- in aluminum alloys 377
- in copper alloys 478(T), 484(T)
- in titanium alloys 419

Germanium

- in copper alloys 478(T), 484(T)
- in titanium alloys 419

Gold

- in copper alloys 478(T), 484(T)
- in palladium alloys 566(F), 568, 605(T),
606, 607(F), 608
- in platinum alloys 558(F), 565, 604(F)
- in silver alloys 599(T), 600

Gold and gold alloys

- brazing alloys 556–557, 556(T)
- compositions 556(T), 602(T)
- dental alloys 556
- electrical contact alloys 556, 601–603, 602(T)
- jewelry alloys 555–556
- properties 551(T), 602(T)

Grain boundaries, nature of 5(F)**Gray irons**

- alloying elements 24–27
- alloying practices 27–30
- annealing 50–51, 51(T)
- applications 23, 23–24(T)
- austenitic nickel-alloyed 59–60, 59(T), 60(F)
- classes 21–23
- composition control 23–27
- corrosion resistance 47–50, 57–59, 57(F)
- creep and stress-rupture 45–47, 48(F), 49(F)
- elevated-temperature properties 34–47
- flame hardening 53–54
- graphite morphology 22(F)
- growth and scaling 35–40, 36(F), 37(F),
38(F), 39(F)
- hardenability 31(T), 53, 54(T)
- high-silicon 55, 57–59, 57(F), 58(F,T)
- high-temperature service 55, 57, 57(F), 58(F)
- hot hardness 41–42, 44–45, 45(F), 46(F),
47(F)
- inoculation 32–34, 33–34(F)
- normalizing 52, 52(T), 53(F)
- properties 30–32, 31(F,T)
- stress relieving 54–55, 56(F)
- tensile properties, at elevated
temperatures 40–41, 41(F), 42(F), 43(F),
44(F)
- trace elements 27, 28(T)

H**Hafnium**

- in molybdenum alloys 310(T), 311(T), 312

- in nickel alloys 511
- in niobium alloys 321(T), 322(F), 323(F)
- in superalloys 292(F), 301, 302(T)
- in tantalum alloys 325(T)

Hardmetals. See Cemented carbides**Heat-resistant alloys. See Ordered**

- intermetallics; Refractory metal alloys;
- Stainless steels; Superalloys

Helium, in superalloys 302(T)**High-alloy white irons**

- alloy grades 107–110, 108(T)
- alloying elements 110–111, 112(F),
113–119, 113(F), 116(F), 118(F)
- applications, abrasion-resistant 108, 110
- compositions 108(T)
- corrosion resistance 108–109, 116(F)
- hardness 107, 108(T)
- inoculants 119
- microstructure 109(F)

High-strength low-alloy steels

- applications 194, 197, 198–199(T)
- categories 193–194
- compositions 195–196(T)
- forging steels 207–209, 207(F)
- microalloying additions 197–206,
198–199(T), 200(F), 201(T), 202(F), 205(F)
- processing characteristics 206–209, 207(F)

Hydrogen

- in aluminum alloys 377–379, 378(F)
- in carbon and alloy steels 142, 156, 157
- in ductile irons 69(T)
- in gray irons 28(T)
- in malleable irons 103(T)
- in superalloys 302(T)
- in titanium alloys 422(T), 430

I**Indium**

- in aluminum alloys 379
- in copper alloys 478(T)
- in lead alloys 529–530(T)
- in magnesium alloys 450(F)

Iridium

- in copper alloys 478(T)
- in noble metal alloys 557, 558(F), 560(F),
565, 566(F), 568, 569, 603–605, 604(F),
605(T), 607(F)
- properties 551(T)

Iron

- in aluminum alloys 379, 379(F), 387–388,
405–406
- in cobalt alloys 542(T), 548(T)
- in copper alloys 463, 473, 478(F,T), 487
- in low-expansion alloys 587–595
- in magnesium alloys 438, 441, 442(F),
443(F), 444(T), 445(T), 446(T), 450

in magnetic alloys 614–632
 in nickel alloys 498–500(T), 502(T),
 504–505, 507–508, 512, 513, 514, 516,
 518–519
 in ordered intermetallics 339(T)
 in solder alloys 535(T), 537
 in superalloys 295–296(T), 296, 297(T)
 in titanium alloys 420, 422(T), 430
 in tungsten alloys 318–319
 in zinc alloys 521(T), 522(T), 524, 525(T)

Iron aluminides. *See* Ordered intermetallics

Iron-nickel alloys. *See* Low-expansion alloys;
 Magnetic alloys

L

Lanthanum

in cobalt alloys 547(T)
 in superalloys 293(F), 294(T), 302(T)

Lead

in aluminum alloys 379, 404, 411
 in carbon and alloy steels 124(T), 141, 184
 in copper alloys 458(T), 460(T), 461(T),
 465, 466, 468, 469(T), 470, 471–472, 474,
 476–477, 478(T), 487, 488, 489–492,
 489(F), 490(F), 492–493, 493–494
 in ductile irons 69(T), 72
 in gray irons 28(T)
 in magnesium alloys 442(F), 450(F)
 in malleable irons 103(T)
 in nickel alloys 518
 in solder alloys 534–536, 535(T)
 in superalloys 302(T)
 in tin-base bearing alloys 539
 in zinc alloys 521(T), 522(T), 525, 525(T)

Lead, tin, and their alloys

alloying elements 529–534
 applications 528–529
 battery grid alloys 530–531, 531(T)
 bearing alloys 532–534, 533(T), 538–539,
 539(T)
 compositions 529–530(T), 531(T), 532(T),
 533(T), 535(T), 539(T)
 impurities in solders 536–538
 solder alloys 534–538, 535(T)
 type metals 531, 532(T)

Lithium

in aluminum alloys 380, 390, 401–402, 413
 in lead alloys 529–530(T)
 in magnesium alloys 434(T), 438–439,
 449–450, 450(F)
 in silver alloys 551, 552(T)

Low-expansion alloys

applications 587
 compositions 592(T), 593(T), 595(T)
 hardenable 594–595, 594(T), 595(T)
 high-strength 595, 595(T)

iron-cobalt-chromium 594
 iron-nickel 587–592, 588(F), 589(F),
 590(F), 591(F), 592(T)
 iron-nickel-chromium 589(F), 592–593,
 593(T)
 iron-nickel-cobalt 589(F), 593, 594(F)

M

Magnesium

in aluminum alloys 356(T), 357(T), 361,
 362, 365–366, 368(F,T), 369(F), 370(F),
 374–376, 375(F), 380–382, 381(F),
 385–387, 386(F), 387(F), 389, 400(F),
 402–403, 406, 408–409, 409(F), 410,
 412–413, 415
 in compacted graphite irons 94
 in copper alloys 478(T)
 in ductile irons 69(T), 70, 73
 in malleable irons 103(T)
 in nickel alloys 517
 in superalloys 302(T)
 in zinc alloys 522(T), 524, 526

Magnesium and magnesium alloys

alloying elements 438–452
 alloying practices 437
 applications 432–433, 433(F)
 castability 438–442
 commercial alloy systems 435–437, 436(T)
 compositions 436(T)
 corrosion behavior 442–450, 442(F),
 443(F), 444(T), 445(F,T), 446(T)
 designations, alloys and tempers 434,
 434(T), 435(T)
 die casting alloys 436(T), 440–442, 444(T)
 formability 452
 machinability 452
 processing 438–440, 451–452
 product forms 433(F), 434–435
 properties 432, 436(T), 438–442, 450,
 450(F)
 stress-corrosion cracking 446–450, 446(F),
 447(F), 448(F), 449(F)
 weldability 451–452, 451(T)

Magnetic alloys

alloying elements 616–618, 617(F),
 618(F)
 Alnicos 629(T), 630, 630(T)
 applications 615, 629–630, 631(T)
 cobalt/rare-earth alloys 629(T), 630(T),
 631
 compositions 628–629, 629(T)
 ferritic stainless steels 627
 ferromagnetic properties 615–618,
 616(F), 617(F), 618(F), 620(F,T), 621(T),
 622(F), 624(F), 625(F), 626–627(T),
 628(F), 629(T), 630(T)

Magnetic alloys (continued)

- high-purity and commercially pure irons 618–619
- impurities 615–616, 616(F)
- iron-cobalt alloys 625–626, 625(F), 626–627(T)
- low-carbon steels 619
- magnetically soft metals and alloys 614–626
- neodymium-iron-boron alloys 629(T), 630(T), 632
- nickel-iron alloys 622–625, 622(F), 623(F), 624(F)
- permanent magnet alloys 627–632, 628(F), 629(T), 630(T), 631(T)
- phosphorus irons 619, 620(F,T)
- silicon steels (flat-rolled products) 620–621, 621(T)

Malleable irons

- alloying elements . . . 101–102, 103–104(T), 104–105
- annealing 100–101
- applications 101
- compositions 102(T)
- metallurgical control 101–102, 104
- microstructure 100, 101(F)
- properties 104–105, 105(F), 106(F)

Manganese

- in aluminum alloys 356(T), 357(T), 360, 368(F,T), 370(F), 376, 376(F), 380, 381(F), 382–383, 382(F), 388–389, 400(F), 402, 403, 406–407, 409(F), 410, 411
- in austenitic manganese steels 242, 243–248, 244(F), 247(F), 252–253
- in carbon and alloy steels 123, 124(T), 125(T), 127, 128, 129, 130, 132, 137, 150, 151(F), 152, 152(F), 159, 159(F), 160(F), 175, 175(T), 178–179, 188
- in cobalt alloys 542(T)
- in compacted graphite irons 93, 98
- in copper alloys . . . 458(T), 469(T), 472–473, 477, 478(T), 483, 484(T), 487
- in ductile irons . . . 65–66(T), 69(T), 70, 71(F), 72, 77(F), 79(T), 80(T)
- in gray irons . . . 26–27, 31(T), 51(T), 52(T), 59(T)
- in high-alloy white irons . . . 108(T), 113–114
- in high-strength low-alloy steels . . . 193, 194, 201, 201(T), 209
- in low-expansion alloys 588, 590(F), 592(T), 593(T)
- in magnesium alloys . . . 434(T), 435, 436(T), 437, 439, 441, 442(F), 444(T), 446(T), 449, 450(F)
- in magnetic alloys . . . 617(F), 618(F), 619, 620
- in malleable irons 102, 102(T), 103(T)
- in nickel alloys 498–500(T), 502, 517

- in silver alloys 551, 552(T)
- in stainless steels 257, 258(F), 263(T), 264(F), 265(T), 266(T), 268(T), 269(T), 270, 282(T)
- in titanium alloys 420, 430, 431
- in tool steels . . . 210, 211–212(T), 215, 220, 221, 222
- in zinc alloys 524–525

Manganese steels, austenitic. *See* Austenitic manganese steels**Maraging steels**

- age hardening 237–238
- applications 235
- characteristics 234
- commercial alloys 235–236
- compositions 236(T)
- hot workability 240–241
- martensite transformation 236–237
- mechanical properties 235(F), 238–239, 238(T)
- stress-corrosion cracking 239, 239(F), 240(F)
- thermal embrittlement 239–240
- weldability 240

Mechanical properties, overview 3–8**Mercury**

- in aluminum alloys 383
- in copper alloys 478(T)
- in silver alloys 553–555

Microalloyed steels. *See* High-strength low-alloy steels**Molybdenum**

- in aluminum alloys 383
- in austenitic manganese steels 243(T), 249(F), 250, 252
- in carbon and alloy steels 124(T), 130, 132, 139, 155, 159, 162, 163, 164–169, 166(F), 173–174, 175(T), 176, 179, 185, 190
- in cermets 574, 582, 585
- in cobalt alloys 542(T), 544, 547(T), 548(T), 549
- in compacted graphite irons . . . 94, 98, 98(F)
- in ductile irons . . . 69(T), 72, 73, 77(F), 78(F), 79(F,T), 80(T), 87, 88–89, 88(F), 89(F)
- in gray irons . . . 28(T), 30, 31(T), 32, 43(F), 46(F), 48(F), 50, 52(T)
- in high-alloy white irons . . . 107, 108, 108(T), 109, 117–119, 118(F)
- in high-strength low-alloy steels . . . 193, 203
- in low-expansion alloys 588
- in magnetic alloys 617(F), 618, 624–625
- in malleable irons 103(T), 105
- in maraging steels . . . 234, 236, 236(T), 238, 239
- in nickel alloys . . . 498–500(T), 502(T), 504, 505–506, 508–509, 511, 512, 513, 516
- in niobium alloys . . . 321(T), 322(F), 323(F)

- in ordered intermetallics 339(T), 344(T)
 - in rhenium-bearing alloys 334
 - in silver-base composites . . 609(T), 610–611, 612
 - in stainless steels 257, 258(F), 260(T), 261(T), 262(F), 263(T), 264(F), 265(T), 267(F), 268(T), 269(T), 270, 272(F), 273(F), 274(F), 276(F,T), 277(T), 282(F,T), 285(F)
 - in superalloys 292(F), 293(F), 294(T), 295–296(T), 297(T), 305(T)
 - in tantalum alloys 325(T), 331–332, 332(T)
 - in titanium alloys 419(T), 420, 422(T), 426(F), 427, 431
 - in tool steels 210, 211–212(T), 213–214, 215, 219, 220, 222, 223, 224, 225, 227, 230, 233
 - in tungsten alloys 315, 316(T), 317(F)
 - Molybdenum and molybdenum alloys**
 - alloying elements 312–313
 - carbide-strengthened 310, 310(T), 312
 - classes 310–311
 - compositions 310(T)
 - dispersion-strengthened 310, 310(T), 313
 - properties 309, 309(T), 311(T), 312(F)
 - solid-solution 310, 310(T), 313
- N**
- Neodymium**, in magnetic alloys 629(T), 630(T), 632
 - Nickel**
 - in aluminum alloys 366, 383, 404
 - in austenitic manganese steels 243(T), 249(F), 251
 - in carbon and alloy steels 124(T), 130, 132–133, 139, 155, 162, 162(F), 164–169, 165(F), 166(F), 167(F), 168(F), 172(T), 175(T), 176, 179, 190
 - in cemented carbides and cermets 573, 574, 582, 582(F), 583, 583(F)
 - in cobalt alloys 542(T), 547(T), 548–549, 548(T)
 - in compacted graphite irons 95(F), 98, 98(T)
 - in copper alloys 458(T), 459(T), 460(T), 461(T), 463, 464, 467–468, 469(T), 475, 476, 478(F,T), 482, 483, 484(T), 485(F), 486, 488(T), 493
 - in ductile irons 69(T), 72, 73, 76(F), 78(F), 79(F,T), 80(T), 81–86, 82(T), 83(F), 84(F,T), 85(F,T), 86(F)
 - in gold alloys 555–556, 556(T), 557, 602, 602(T)
 - in gray irons 28(T), 29, 30, 31(T), 49, 51(T), 52(T), 59–60, 59(T), 60(F)
 - in high-alloy white irons 107, 108, 108(T), 109, 115–117
 - in high-strength low-alloy steels 193
 - in low-expansion alloys 587–595, 588(F), 589(F), 590(F), 591(F), 592(T), 593(T), 594(F,T), 595(T)
 - in magnesium alloys 439, 441, 442(F), 443(F), 444(T), 445(T)
 - in magnetic alloys 617(F), 618(F), 622–625, 622(F), 623(F), 624(F), 628, 629(T), 630, 630(T)
 - in malleable irons 103(T), 105
 - in maraging steels 234, 236, 236(T), 237, 237(F)
 - in palladium alloys 566(F), 568, 605(T), 606, 607(F)
 - in platinum alloys 558(F), 562, 563(F), 564(F), 565, 604(F)
 - in silver alloys 551, 552(T), 599, 599(T), 600
 - in silver-base composites 609(T), 612
 - in solder alloys 537
 - in stainless steels 257, 258(F), 260(T), 261(T), 263(T), 264(F), 265(T), 266(T), 267(F), 268(T), 269(T), 270, 276(T), 277(T), 280(F), 281(F), 284(F), 288(T)
 - in superalloys 293(F), 294(T), 295–296(T), 296–298, 297(T), 305(T)
 - in titanium alloys 420, 426(F), 427
 - in tool steels 211–212(T), 221, 223
 - in tungsten alloys 318–319
 - in zinc alloys 522(T), 524–525
 - Nickel aluminides**. *See* Ordered intermetallics
 - Nickel and nickel alloys**
 - alloying elements 501(F), 502(T), 507–519, 508(F)
 - applications 496
 - carbides 510–512
 - characteristics 495–496
 - classification 496–507, 498–500(T), 501(F)
 - compositions 498–500(T)
 - corrosion resistance 502(T), 503(F), 507–512, 508(F)
 - forgeability 514
 - formability 513–514, 514(F)
 - impurities 501–502
 - intermetallic phases 512, 513, 514, 515
 - machinability 518–519
 - weldability 515–518
 - Niobium**
 - in aluminum alloys 383
 - in carbon and alloy steels 130, 132, 140, 156, 157(F), 159, 163, 175(T), 179, 208
 - in cobalt alloys 547(T)
 - in high-strength low-alloy steels 193, 194, 202–203, 202(F), 205(F), 206
 - in low-expansion alloys 595, 595(T)

Niobium (continued)

- in magnetic alloys 630
- in maraging steels 236(T)
- in nickel alloys 498–500(T), 502(T),
509–510, 511
- in ordered intermetallics 339(T), 343(T),
344(T)
- in stainless steels 257, 258(F), 261(T),
262(F), 263(T), 264(F)
- in superalloys 292(F), 295–296(T)
- in tantalum alloys 325(T), 332
- in titanium alloys 420, 431

Niobium and niobium alloys

- alloying elements 321–324, 322(F), 323(F)
- classes 320–321
- compositions 321(T)
- properties 309(T), 311(T), 320

Niobium carbide, in cemented carbides and

- cermets 573, 574, 575, 576, 577(F), 583

Nitrogen

- in austenitic manganese steels 251–252
- in carbon and alloy steels 141, 154–155,
156, 159, 159(F), 175(T), 176, 180
- in ductile irons 69(T)
- in gray irons 28(T)
- in high-strength low-alloy steels 193, 197,
204, 209
- in magnetic alloys 615–616, 618–619
- in malleable irons 103(T)
- in nickel alloys 502(T)
- in stainless steels 258(F), 261(T), 263(T),
264(F), 268(T), 269(T), 270–271, 274(F),
277(T)
- in superalloys 293(F), 294(T), 302(T)
- in titanium alloys 419, 422(T), 428
- in tool steels 216, 230

Noble metal alloys. See also Electrical contact

- alloys; Gold and gold alloys; Palladium
and palladium alloys; Platinum and
platinum alloys; Silver and silver alloys
overview 550
- properties 551(T)

Nodular iron. See Ductile irons**O****Ordered intermetallics**

- alloying elements 339–340, 342–343,
345–346, 346–348
- applications 341, 343, 344
- atomic arrangement 337(F)
- compositions 339(T), 343(T), 344(T), 345,
346
- iron aluminides 342–344
- nickel aluminides 339–341
- overview 337–338

- properties 338(T), 340, 340(F), 345–346,
345(T), 346–348, 346(T), 347(T)
- titanium aluminides 344–348

Osmium

- in noble metal alloys 558(F), 569, 604(F),
607(F)
- properties 551(T)

Oxygen

- in carbon and alloy steels 142, 156–157,
175(T), 176, 180
- in copper alloys 478(T), 487, 601, 601(T)
- in ductile irons 69(T)
- in magnetic alloys 615–616
- in malleable irons 103(T)
- in superalloys 302(T)
- in titanium alloys 419, 422(T), 428, 429,
429(F), 431

P**Palladium**

- in chromium alloys 568
- in copper alloys 478(T)
- in gold alloys 556, 556(T), 557
- in platinum alloys 557, 558(F), 559(F),
565, 604(F), 605, 605(T)
- in silver alloys 598(F), 599(T), 600
- in titanium alloys 420, 426(F), 427, 568

Palladium and palladium alloys

- alloying elements 566–568
- applications 567–568
- compositions 605(T)
- corrosion resistance 568
- electrical contact alloys 603, 605(T),
606–608, 607(F)
- properties 551(T), 566(F), 567(F), 568(F),
605(T)

Permanent magnet alloys. See Magnetic alloys**Phase diagrams**

- aluminum-silicon 364(F)
- iron-carbon 25(F)
- iron-nickel 237(F)
- magnesium-tin 11(F)
- tin-lead 535(F)

Phosphorus

- in aluminum alloys 383–384, 396, 397,
398(F), 412
- in austenitic manganese steels 243(T), 248,
253
- in carbon and alloy steels 125(T),
128–129, 142, 153, 164–169, 165(F),
166(F), 168(F), 172(T), 175(T), 176, 179,
184, 189
- in compacted graphite irons 93, 97
- in copper alloys 458(T), 460(T), 461(T),
462, 464, 466, 478(F,T), 481–482, 486,
487, 494, 601(T)

Phosphorus (continued)

- in ductile irons 65–66(T), 69(T), 72
- in gray irons 25–26, 51(T), 52(T)
- in high-alloy white irons 108(T), 114
- in high-strength low-alloy steels 194
- in magnetic alloys . . . 618, 619, 620, 620(F,T)
- in malleable irons 102(T), 103(T)
- in nickel alloys 518
- in solder alloys 537
- in stainless steels . . . 262(F), 263(T), 264(F),
265(T), 266(T), 267(F), 268(T), 283(F)
- in superalloys 293(F), 294(T), 302(T)
- in tool steels 215

Physical properties, overview 4, 12–14

Platinum

- in copper alloys 478(T)
- in gold alloys 602, 602(T), 603
- in magnetic alloys 628, 629(T), 630(T)
- in palladium alloys 566(F), 568, 605(T),
606, 607(F), 608
- in silver alloys 598(F), 599(T), 600
- in titanium alloys 427

Platinum and platinum alloys

- alloying elements 557–565
- applications 557–558, 561–563, 565
- compositions 605(T)
- corrosion resistance 565
- dispersion-strengthened . . . 562–565, 564(T),
565, 565(F)
- electrical contact alloys . . . 603–605, 604(F),
605(T)
- properties . . . 551(T), 558(F), 559(F), 560(F),
561(F,T), 562(F), 563(F), 564(F,T),
565(F), 605(T)

Potassium

- in molybdenum alloys 310(T), 311(T)
- in tungsten alloys 315

Precipitation, coherent and noncoherent . . 7(F)

Processing properties, overview 4, 10–12

R

Rare earths. *See also* Cerium; Lanthanum;

Neodymium; Samarium; Yttrium

- in carbon and alloy steels 156, 180
- in compacted graphite irons 94
- in ductile irons 69(T)
- in high-strength low-alloy steels 194
- in magnesium alloys . . . 434(T), 435, 436(T),
439, 441, 448
- in magnetic alloys . . . 629(T), 630(T), 631–632
- in nickel alloys 502(T)

Refractory metal alloys. *See also* Molybdenum and molybdenum alloys; Niobium and niobium alloys; Rhenium and rhenium-bearing alloys; Tantalum and tantalum alloys; Tungsten and tungsten alloys

- applications 309
- property characteristics 308, 309(T)

Rhenium

- in molybdenum alloys . . . 310(T), 311(T), 313
- in superalloys 292(F), 293(F), 294(T)
- in tungsten alloys 315, 317(F), 318(F)

Rhenium and rhenium-bearing alloys

- alloying elements 334
- properties 309(T), 311(T), 333

Rhodium

- in copper alloys 478(T)
- in noble metal alloys 557–558, 558(F),
561, 561(T), 562–563, 564(T), 565,
565(F), 566(F), 568, 569, 604(F), 607(F)
- properties 551(T)
- in titanium alloys 427

Ruthenium

- in noble metal alloys . . . 558(F), 561, 561(F),
562(F), 565, 566(F), 569, 604(F), 605,
605(T), 606, 607(F)
- properties 551(T)
- in titanium alloys 420, 426(F)

S

Samarium, in magnetic alloys 629(T), 631

Selenium

- in carbon and alloy steels 189
- in copper alloys . . . 458(T), 473, 478(T), 487,
492
- in stainless steels 257, 258(F), 262(F),
264(F), 267(F)
- in superalloys 302(T)

Service properties, overview 4, 8–10

Silicon

- in aluminum alloys 356(T), 357(T),
360–361, 362, 364–365, 364(F), 368(F,T),
379(F), 380–382, 384, 388, 400(F), 402,
403, 404–407, 405(T), 407(F), 410,
411–412, 413, 414, 416
- in austenitic manganese steels . . . 243(T), 248
- in carbon and alloy steels 123, 124(T),
132, 133, 138, 153, 169, 172(T), 174,
174(F), 175(T), 176, 179, 190
- in cobalt alloys 542(T)
- in compacted graphite irons 93, 93(F),
96–97, 97(F)
- in copper alloys 458(T), 459(T), 460(T),
461(T), 467, 469(T), 473, 475, 478(F,T),
482, 487, 488, 488(T)
- in ductile irons 65–66(T), 69(T), 70, 73,
79(T), 80(T), 86–89, 87(F), 88(F), 89(F)
- in gray irons 24–26, 31(T), 47–48, 50–51,
52(T), 55, 57–59, 57(F), 58(F,T), 59(T)
- in high-alloy white irons . . . 108(T), 110, 111,
112(F), 113, 115
- in high-strength low-alloy steels 209

Silicon (continued)

- in low-expansion alloys. . . 588, 592(T), 593(T)
- in magnesium alloys. . . 434(T), 436(T), 439, 441, 442(F)
- in magnetic alloys. 617, 617(F), 618(F), 620–621, 621(T)
- in malleable irons. . . 102, 102(T), 103(T), 104
- in molybdenum alloys. 310(T), 311(T)
- in nickel alloys . . . 498–500(T), 502(T), 507, 509, 512, 514, 517
- in stainless steels 257, 263(T), 264(F), 265(T), 266(T), 268(T), 269(T), 282(T)
- in superalloys 293(F), 294(T)
- in titanium alloys. . . 419(T), 420, 421(F), 430
- in tool steels. . . 211–212(T), 214, 219, 221, 222
- in tungsten alloys 315
- in zinc alloys. 524–525

Silver

- in aluminum alloys. 384
- in copper alloys 462, 478(F,T), 484(T)
- in gold alloys . . . 555–556, 602–603, 602(T)
- in lead alloys 529–530(T)
- in magnesium alloys. . . 434(T), 435, 436(T), 439, 442(F), 450(F)
- in palladium alloys 566(F), 567–568, 567(F), 568(F), 605(T), 606, 607(F), 608
- in platinum alloys. 565
- in solder alloys. 535(T), 538
- in superalloys 302(T)

Silver and silver alloys

- brazing alloys. 551–552, 552(T)
- compositions. 552(T), 599(T)
- corrosion behavior 553
- dental amalgam. 553–555
- electrical contact alloys. . . 552–553, 597–600, 598(F), 599(T), 608–612, 609–610(T), 612(F)
- jewelry, tableware, and coinage 553
- properties 551(T), 553, 554(F), 599(T)

Slip, formation stages 4(F)

Sodium

- in aluminum alloys . . 384, 392–395, 394(F), 395(F), 396(F), 412
- in magnesium alloys 442(F)

Solder alloys. *See* Lead, tin, and their alloys

Solid-solution mechanisms 6(F)

Special-purpose alloys. *See* Cemented

- carbides and cermets; Electrical contact alloys; Low-expansion alloys; Magnetic alloys

Spheroidal-graphite iron. *See* Ductile irons

Stainless steels

- alloying elements 269–289
- applications. 258–259
- austenitic . . 261–263, 263(T), 264(F), 265(T), 271–273, 272(F), 275, 275(T), 276(F), 278–283, 279(F), 280(F), 281(F), 282(F,T), 283(F), 287–288

- compositions 260(T), 261(T), 263(T), 265(T), 266(T), 268(T), 269(T)
- corrosion behavior 268–289
- crevice corrosion. . . 275–276, 276(F,T), 277(T)
- designations 257–258, 258(F)
- duplex . . 265–267, 268(T), 274, 276, 277(T), 284–286, 285(F)
- families . . . 259–268, 262(F), 264(F), 267(F)
- ferritic . . . 259–261, 260(T), 261(T), 262(F), 273–274, 273(F), 274(F), 275–276, 275(T), 276(T), 277(T), 283–284, 284(F), 285(F), 289, 627
- martensitic 263, 265, 266(T), 267(F), 274–275, 275(T)
- oxidation resistance 286–289, 286(F), 287(F), 288(F,T)
- pitting corrosion . . 271–275, 272(F), 273(F), 274(F), 275(T)
- precipitation-hardening . . . 267–268, 269(T), 274–275, 275(T)
- sensitization and intergranular corrosion 277–278, 278(F)
- stress-corrosion cracking . . 278–286, 279(F), 280(F), 281(F), 282(F,T), 283(F), 284(F), 285(F)

Strontium

- in aluminum alloys . . 384, 392–395, 394(F), 395(F), 412
- in lead alloys 529–530(T)

Sulfur

- in aluminum alloys. 384
- in austenitic manganese steels. 252
- in carbon and alloy steels 125(T), 128–129, 142, 153, 153(F), 154(F), 175(T), 176, 179, 184, 187–188, 187(T), 189, 191
- in compacted graphite irons 94, 95(F)
- in copper alloys 462, 478(T), 487, 490
- in ductile irons. 65–66(T), 69(T), 70–71
- in gray irons 26, 27(F), 52(T)
- in high-alloy white irons. . . 108(T), 113–114
- in high-strength low-alloy steels. 209
- in magnetic alloys 615–616, 618–619
- in malleable irons 102, 102(T), 103(T)
- in nickel alloys . . . 498(T), 502, 502(T), 514, 518
- in solder alloys 537
- in stainless steels. 257, 258(F), 262(F), 263(T), 264(F), 265(T), 266(T), 267(F), 268(T)
- in superalloys 302(T)
- in tool steels. 216

Superalloys

- alloying elements 292(F), 293, 293(F), 294(T), 299–303, 302(T)
- applications. 290–291
- carbides 300–301, 300(F)
- characteristics. 290

cobalt-base 298
 compositions 295–296(T), 297(T),
 305(T)
 iron-nickel-base 296
 mechanical alloying 303–305, 303(F),
 305(F,T)
 nickel-base 296–298, 300(F)
 oxidation resistance 301
 phases 293
 properties and microstructure 298–303,
 300(F)
 systems 294–298
 trace elements 301–303, 302(T)
 weldability 305–307, 306(F)
Surface alloying, overview 16–17

T

Tantalum

in cobalt alloys 547(T), 548(T)
 in nickel alloys 509–510, 511
 in niobium alloys 321(T), 323(F)
 in stainless steels 258(F), 262(F), 263(T),
 264(F), 301
 in superalloys 292(F), 293(F), 294(T),
 297(T), 305(T)
 in titanium alloys 420, 427, 431

Tantalum and tantalum alloys

alloying elements 325–333
 compositions 325(T)
 corrosion resistance 326–333, 327(F,T),
 328(F), 330(F), 332(T)
 properties 309(T), 311(T), 324, 325–326,
 326(T)

Tantalum carbide, in cemented carbides and
 cermets 573, 574, 575, 575(T), 576,
 577(F,T), 580, 583

Tellurium

in carbon and alloy steels 189
 in copper alloys 462, 478(T), 487, 490, 492
 in ductile irons 69(T)
 in gray irons 28(T)
 in high-alloy white irons 119
 in malleable irons 103(T), 104
 in superalloys 302(T)

Thallium

in magnesium alloys 450(F)
 in superalloys 302(T)

Thorium

in magnesium alloys 434(T), 435, 436(T),
 437, 439, 450(F)
 in superalloys 293(F), 294(T)
 in tungsten alloys 317–318

Tin

in aluminum alloys 384–385, 404
 in carbon and alloy steels 142, 157,
 164–169, 165(F), 166(F), 168(F)

in compacted graphite irons 94, 95(F),
 96(F), 98
 in copper alloys 458(T), 459(T), 460(T),
 461(T), 463, 465–466, 469(T), 471–472,
 474–475, 476, 478(F,T), 481–482, 484(T),
 486, 601(T)
 in ductile irons 69(T), 72
 in gray irons 27, 28(T), 32, 46(F), 47(F)
 in lead alloys 529–530(T), 532(T), 533(T)
 in magnesium alloys 439, 442(F), 450(F)
 in magnetic alloys 617(F)
 in malleable irons 103(T)
 in silver alloys 551, 552(T), 554–555
 in solder alloys 534–536, 535(T), 538
 in stainless steels 282(T)
 in titanium alloys 419(T), 420, 422(T),
 428, 431
 in zinc alloys 522(T), 525

Tin and tin alloys. *See* Lead, tin, and their
 alloys

Tin oxide, in silver-base composites 609(T),
 612

Titanium

in aluminum alloys 385, 390–392, 391(F),
 410
 in austenitic manganese steels 251–252
 in carbon and alloy steels 140, 156, 159,
 163, 175(T), 176, 179
 in cobalt alloys 547(T), 548(T)
 in compacted graphite irons 94
 in copper alloys 478(T), 484(T)
 in ductile irons 69(T), 72
 in gray irons 28(T), 50
 in high-strength low-alloy steels 193, 194,
 204–206, 205(F), 208
 in low-expansion alloys 594–595, 594(T),
 595(T)
 in magnetic alloys 617(F), 629(T), 630
 in malleable irons 104(T)
 in maraging steels 234, 236, 236(T), 237,
 238–239, 240–241
 in molybdenum alloys 310(T), 311(T)
 in nickel alloys 498–500(T), 502(T), 503,
 510, 511, 513, 517
 in niobium alloys 321(T), 322(F), 323(F)
 in ordered intermetallics 344(T)
 in stainless steels 257, 258(F), 261(T),
 262(F), 263(T), 264(F), 269(T), 274(F)
 in superalloys 292(F), 293(F), 294(T),
 295–296(T), 297(T), 301, 305(T), 306(F)
 in tantalum alloys 332–333
 in zinc alloys 521(T), 526

Titanium aluminides. *See* Ordered
 intermetallics

Titanium and titanium alloys

alloying elements 419–431, 419(T)
 alpha and near- alloys 419–420, 419(T),
 422–423, 422(T), 428–430

Titanium and titanium alloys (continued)

- alpha-beta alloys 422(T), 423–424, 430–431
- applications 417–418
- beta alloys 419–420, 419(T), 422(T), 424, 431
- compositions 422(T)
- corrosion behavior 424–431, 426(F,T)
- general characteristics 417
- physical metallurgy 418–419
- processing characteristics . . 421–424, 422(T)
- properties 422(T)
- stress-corrosion cracking . . 427–431, 428(T), 429(F), 430(F)
- unalloyed grades 421–422, 422(T), 427–428

Titanium carbide, in cemented carbides and

- cermets . . 573, 574, 575(T), 576, 577(F,T), 580, 582–585, 582(F), 584(T), 585(T)

Titanium carbonitride, in cermets 574, 582–583, 583(F)**Tool steels**

- alloy carbides 217–218, 218(T), 219(F), 223–233, 225(T), 229(T), 231(F), 232(F)
- alloying elements 214–233
- applications 210, 221, 222, 223
- classification and characteristics . . 211–213, 211–212(T), 219, 220, 222–223
- compositions . . 211–212(T), 225(T), 229(T), 233(T)
- hardness 217(F), 218(F), 219(F), 226, 226(F), 228(F)
- P/M cold-work tool steels . . 227–230, 229(T)
- P/M high-speed tool steels 223–227, 225(T), 226(F)
- P/M wear/corrosion-resistant tool steels 230, 233, 233(T)
- wear resistance . . 217–218, 219(F), 224–226, 228(F), 230, 233, 233(T)
- wrought cold-work tool steels 220–222
- wrought high-speed tool steels 213–218
- wrought hot-work tool steels 219–220

Tungsten

- in carbon and alloy steels 124(T), 141
- in cobalt alloys . . . 542(T), 544, 546, 547(T), 548(T)
- in composite electrical contact materials . . . 608–612, 609–610(T)
- in gray irons 28(T)
- in low-expansion alloys 588
- in magnetic alloys . . . 617(F), 629(T), 630(T)
- in molybdenum alloys . . 310(T), 311(T), 313
- in nickel alloys . . . 498–500(T), 502(T), 506, 509, 511, 512, 513
- in niobium alloys . . . 321(T), 322(F), 323(F)
- in platinum alloys 558(F), 561–562, 562(F), 563(F)

- in rhenium-bearing alloys 334
- in stainless steels 267(F), 268(T)
- in superalloys 292(F), 293(F), 294(T), 295–296(T), 297(T), 305(T)
- in tantalum alloys 325(T), 327–331, 327(F), 328(F), 330(F)
- in titanium alloys 427
- in tool steels . . . 210, 211–212(T), 213–214, 215, 219–220, 221, 222, 224, 225, 227

Tungsten and tungsten alloys

- alloying elements 315–319
- classes 314–315
- dispersion-strengthened 314, 317–318
- doped tungsten 314, 315, 316(F)
- heavy tungsten 314, 318–319, 319(F)
- properties 309(T), 311(T), 313–314, 316(T), 317(F), 318(F), 319(F)
- solid-solution 314, 315

Tungsten carbide

- in cemented carbides 573–582, 575(T), 576(F), 577(F), 579(F), 580(F), 581(F), 582(F)
- in composite electrical contact materials . . . 608–611, 609–610(T)

V**Vanadium**

- in aluminum alloys 385, 410
- in austenitic manganese steels 251, 252
- in carbon and alloy steels 124(T), 130, 132, 133, 139–140, 156, 159, 163, 175(T), 176, 179
- in compacted graphite irons 98
- in ductile irons 69(T), 72
- in gray irons 28(T), 31(T), 32, 50
- in high-alloy white irons 119
- in high-strength low-alloy steels . . 193, 194, 197, 200–202, 200(F), 201(T), 203, 204, 205(F), 208
- in magnetic alloys 617, 617(F)
- in malleable irons 104(T)
- in nickel alloys 511
- in niobium alloys . . . 321(T), 322(F), 323(F)
- in stainless steels 267(F)
- in titanium alloys 419(T), 420, 431
- in tool steels . . . 210, 211–212(T), 215–216, 218, 219, 220, 221, 223, 224, 225–226, 227–230

W**White irons, high-alloy. See High-alloy white irons**

Y**Yttrium**

- in cobalt alloys 547(T)
- in magnesium alloys . . . 434(T), 435, 436(T),
440
- in nickel alloys 502(T)
- in superalloys 293(F), 294(T)

Z**Zinc**

- in aluminum alloys 356(T), 362, 366,
368(F,T), 385–387, 386(F), 387(F), 389,
400(F), 403–404, 413, 415
- in copper alloys 458(T), 459(T), 460(T),
461(T), 464–466, 468, 469(T), 471–473,
476, 478(F,T), 480, 482, 483–486, 484(T),
485(F), 486, 492, 601(T)
- in gold alloys 555, 556, 602(T), 603
- in magnesium alloys . . . 434(T), 435, 436(T),
440, 442(F), 446(F), 447–449, 447(F),
448(F), 449(F), 450(F), 451
- in malleable irons 104(T)
- in palladium alloys 605(T), 606, 608

- in silver alloys . . . 551–552, 552(T), 554–555
- in solder alloys 535(T), 537, 538
- in tin-base bearing alloys 539

Zinc and zinc alloys

- alloying elements 522–526
- applications 520–521
- casting alloys 521–525
- compositions 522(T), 523(T), 525(T)
- properties 523(T), 524(F)
- wrought alloys 525–526

Zirconium

- in aluminum alloys 387, 390, 410
- in carbon and alloy steels . . 141, 156, 175(T)
- in cobalt alloys 547(T), 548(T)
- in copper alloys 462, 463(F), 464, 478(T)
- in ductile irons 69(T)
- in high-strength low-alloy steels . . . 193, 194
- in magnesium alloys . . . 434(T), 435, 436(T),
437, 440, 448
- in malleable irons 104(T)
- in molybdenum alloys . . 310(T), 311(T), 312
- in nickel alloys 511, 517
- in niobium alloys . . . 321(T), 322(F), 323(F)
- in ordered intermetallics . . . 339(T), 343(T),
344(T)
- in superalloys . . 293(F), 294(T), 297(T), 301,
302(T)
- in titanium alloys 419(T), 420, 422(T),
427, 429